ECS Configuration Change Request Pages of Pages					
CCR No. 98-0.	568 Logged D	ate 5/7/98	Rev Request Type CCR		
Priority Routine		Emergency X	Affected Release	2.0	Change Class II
Title (description) Upgrade and baseline STK firmware and software					
Documents Affected			Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or Tech Reference		
(COTS Version Baseline)	l .		None		
RTM Change Start New Baseline					
Problem The current microcode load needs to be upgraded in order to fix reported problems with data corruption on D3 tape drives. Also, the StorageTek libraries do not have a baselined list of firmware and software. Such a list is an absolute necessity in order to recover from potential catastrophic events.					
Need Date: 5/13/98					
Proposed Solution The COTS Version Baseline for the STK Powderhorn and STK Wolfcreek should be updated to the following: Firmware (loaded via floppy): SSU 5.1.1 (Cartridge Tape Unit processor), RS 3.01 (microcode for D3), LMU 1.4.03 (Library Management Unit processor) Software (Sun Sparc 5 front end): OS - Solaris 2.5.1 with standard ECS patch set, Dedicated application - ACSLS 5.1 Release notes attached. Upgrades to be accomplished by STK supervised by RTSC or someone appointed by ECS management					
Impact Analysis:		· · · · · ·			
Organizations Affected:	воо 🔲	=	CS Chief Eng	FOS Rel. C	M&O [X] SCDO Arch. ☐
Procurement Science Off	QO Security	Rel. Dev Subcontrct	Rel. A Sys. Eng [X]	Sys Verf Acpt	SCDO AIGII.
Cost:	None X	Small [Medium	Large (Over \$500,000)	
Schedule:	None X	Other			
Additional LOC _			Man-Month	s	
Materials		A 1-0	1	 	
Originator Byron V. Pet	ers	Signature / L	ls.		05/01/98 Date
Office SED/HWE	Office Manager	Rancall	mil		5/1/98 Date
Disposition	Approved	Approved w/Comr	nent Forw	ard	Disapproved
Comments:	CCB Chairperson	Twfu		5/	-/8/98

ORIGINAL

ECS